




Mounting kit VX side panel for LCP VX

6x



M5x12


$M_A = 4Nm$

TX 30

6x



Mounting of side panel holder (same mounting at right and left side of LCP's)
Please refer to the operating instructions of your LCP.



! Break out these two punch-outs !

The side panel has to be turned in a way that the grounding studs protrude into the punch outs that have been broken out.

Finally, mount the side panel with the screws M6x16 (8x) into the existing holes in the side panel (enclosed with side panel articles).

